


2nd November 2022

Local Notice to Mariners N° 038 of 2022
Cardinal Marker Buoys around OS 35 Wreck

Mariners, Owners, Agents and Charterers are advised that Cardinal Marker Buoys have now been placed around the OS 35 wreck in the following positions:

	Latitude	Longitude
North Cardinal	36° 08.259'N	005° 19.900'W
East Cardinal	36° 08.075'N	005° 19.750'W
South Cardinal	36° 07.890'N	005° 19.955'W
West Cardinal	36° 08.060'N	005° 20.145'W



All vessels (commercial and pleasure users alike) are reminded that it is unsafe to navigate within the area demarcated by these buoys.

VTS Manager
Gibraltar Port Authority